

Test Report	No.: SDHL2006008615FT	Date:	Page 1 of 3
The following sample(s) was / v	vere submitted and identified on beha	alf of the client as:	
Sample Description	: OFFICE CHAIR CASTER		
Supplier Item No.	: ITEM NO.: R003		
Manufacturer	:		
Sample Receiving Date	:		

Test Performing Date

Test Result Summary

Test(s) Requested	Result(s)
Clause 16 of ANSI/BIFMA X5.1-2017	PASS
Summary:	

1. For further details, please refer to the following page(s).

Signed for and on behalf of Shunde Branch SGS-CSTC Co., Ltd.

Bill Wang Approved signatory







Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-eDocument.aspx. Attention is drawn to the limitation of liability, indemrification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) tested and such sample(s) are retained for 30 days only. Attention: To check the authenticity of testing / imspection report & certificate, please contact us at telephone:(86-755) 8307 1443, or email: CN.Doccheck@sgs.com

1/fr;f⁴Baiding_European Industrial Park/lia.1 Sturite Suth Reat/Wista Section_Dalarg Town,Sturide_Ristan_Glaragdomg,China 528333 tt (86-757)22805888 ft (86-757)22805888 www.sgsgroup.com.cn 中国・广东・佛山市廢棄区大良街道办事处五沙版和南路1号欧洲工业园一号厂房首局邮编: 528333 tt (86-757)22805888 ft (86-757)22805888 e sgs.china@sgs.com



Test Report

No.: SDHL2006008615FT

Date: Jun.29, 2020

Page 2 of 3

TESTS AND RESULTS

Test Conducted:

Clause 16 of ANSI/BIFMA X5.1-2017 General-Purpose Office Chairs – Tests.

No. of Sample:

5 pieces. For more sample information and pictures, please refer to the following page.

Test and Requirements	Test Results
16 Caster/Chair Base Durability Test - Cyclic	
16.1 Caster/Chair Base Durability Test for Pedestal Base Chairs No loss of service after 2,000cycles over a hard surface with 3 obstacles and 98,000cycles over a smooth hard surface without obstacles under a 122kg (270lbs.) load at a rate of 10 ± 2 cycles per minute. Test stroke is 762 ± 50 mm (30 ± 2 in.) minimum. No part of the caster shall separate from the chair as a result of the application of the 22 N (5 lbf.) force.	PASS
16.2 Caster / Chair Frame Durability Test for Non-pedestal Chairs with Casters No loss of service after 2,000cycles over a hard surface with 2 obstacles and 98,000cycles over a smooth hard surface without obstacles under a 122 kg (270 lb.) load on the seat at a rate of 10 ± 2 cycles per minute. Test stroke is 762 ± 50 mm (30 ± 2 in.) minimum. No part of the caster shall separate from the chair as a result of the application of the 22 N (5 lbf.) force.	N/A

Remark:

1. N/A – Not applicable; N/R – Not requested; N/P – Not provided.

2. For the sample information and pictures, please refer to the following page.



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document cannot be reproduced a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced accept in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the somple(s) tested and such sample(s) are retained for 30 days only. Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone:(86-755) 8307 1443, or email: Ch.Doccheck@sgs.com

1作,f¹BuidingEuropean IndustriaPart/kn.1SturiteStuft Redt,WusteStedon,Dalang Town,Shunde,Fushan,Guangdong,China 528333 tt (86-757)22805888 ft (86-757)22805888 www.sgsgroup.com.cn 中国 ·广东 ·佛山市原德区大良街道办事处五沙颗和南路1号欧洲工业园一号厂房首层 邮编: 528333 tt (86-757)22805888 ft (86-757)22805888 e sgs.china@sgs.com



Test Report

No.: SDHL2006008615FT

Page 3 of 3

SAMPLE INFORMATION AND PICTURES

Date:

Weight: 0.12 kg

Overall Dimensions: 59.97 mm Dia. x 89 mm H

Other Dimensions: /

Sample as Received





End of Report



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <a href="http://www.sgs.com/en/Terms-and-Conditions/Terms-and-Cond

1/f;/fbildingEuropean Industrial Park/No.1 Shunhe South Read, Wasta Section, Dalarag Town, Shunde, Fristran, Guargdong, China 5228333 t (86-757) 22805888 f (86-757) 22805858 www.sgsgroup.com.cn 中国·广东·佛山市颜德区大良街道办事处五沙颜和南路1号欧洲工业园一号厂房首层邮编:528333 t (86-757)22805888 f (86-757)22805888 e sgs.china@sgs.com

View 4